


Electronic Caliper

ZERO/ABS button allows the display to be zero-set at any slider position along the scale.

Cat # SPI15-194-4



- ZERO/ABS button allows the display to be zero-set at any slider position along the scale
- Resolution: 0.0005"/0.01 mm
- Inch/Metric conversion
- Certificate of calibration traceable to NIST included
- Furnished in fitted case



G.A.L. Gage Company

Phone: (269) 465-5750 • Fax: (269) 465-6385 • www.galgage.com
2953 Hinchman Road, P.O. Box 218, Stevensville, Michigan 49127

